

## Installation Instruction

Step 1: Disconnect Power cable on your CNC machine.

Step 2: Disconnect signal cable (DB9) from your CNC machine.

Step 3: Remove your old CRT monitor assembly.

Step 4: Install our new retrofit LCD monitor.

Step 5: Connect signal cable to retrofit LCD monitor.

Step 6: Connect power cable to new retrofit LCD monitor.

Please call us if you have any question:

1-415-682-8685



MS121R43CNCHAAS is a color monitor. We had set it to MDA (black and white) because of the old CRT monitor is monochrome.

However, you can change it to color monitor by following this procedures:

1. Press "MENU" once
2. Press "DOWN" button to select "Color Mode" Tab
3. Press "MENU" button once
4. Press "DOWN" Button to "Color Mode"
5. Press "MENU" button once
6. Press "DOWN" Button once to select color

Looking for technical assistance?

We love to help!

Please visit us online at

[http://store.lcdparts.net/tech-support\\_ep\\_45.html](http://store.lcdparts.net/tech-support_ep_45.html)